



# ENEE4304 Instrumentation & Measurement




L5

## Measurement Errors




## Systematic and Random Errors

- Errors are effects that cause a measured value to differ from its true value.
- Systematic error causes an offset between the mean value of the data set and its true value.
- Random error causes a random variation in measured values found during repeated measurements of a variable.
- Both random and systematic errors affect a system's accuracy.




# Systematic and Random Errors




Low random error  
Low systematic errors

High Precision  
High accuracy



Low random error  
High systematic error


High precision  
Low accuracy



High random error,  
High systematic error


Low precision  
Low accuracy

# Systematic and Random Errors



## Random Errors

- ❑ Random errors in measurements are caused by unpredictable variations in the measurement system.
- ❑ They are usually observed as small perturbations of the measurement to either side of the correct value, i.e. positive errors and negative errors occur in approximately equal numbers for a series of measurements made of the same constant quantity.
- ❑ Therefore, random errors can largely be eliminated by calculating the average of a number of repeated measurements, provided that the measured quantity remains constant during the process of taking the repeated measurements.




## Sources of Systematic Error:

### 1) Zero Drift

- ❑ Zero drift (zero offset) (or bias) causes a constant error over the full range of measurement. Zero drift is normally removable by calibration.



A scale giving a reading when no mass is placed has a zero drift




## Sources of Systematic Error: 2) Scale Error

- Scale error produces an error that is a percentage of the measured quantity

$$e = kx$$

$e$ : Scale Error


$x$ : Measured Variable






Expansion or contraction of the ruler due to temperature



Hardening or softening of the spring used in the scale




## Combined Zero Drift and Scale Error



## Sources of Systematic Error:


### 3) System disturbance due to measurement

- ❑ Disturbance of the measured system by the act of measurement is a common source of systematic error.
- ❑ A mercury-in-glass thermometer, initially at room temperature, and used to measure the temperature of a hot water beaker, would introduce a disturbance (heat capacity of the thermometer) into the hot water and lower the temperature of the water.
- ❑ In nearly all measurement situations, the process of measurement disturbs the system and alters the values of the physical quantities being measured.



#### Example : System Disturbance in electric circuit measurements

- ❑ In the circuit shown, the voltage across resistor  $R_5$  is to be measured by a voltmeter with resistance  $R_m$ . Estimate the disturbance error in the measured voltage in term of  $R_m$ .





**Example : Solution**

- Defining  $I$  as the current flowing in the circuit when the instrument is connected to it, we can write:



$$I = \frac{E_o}{R_{AB} + R_m}$$

and the voltage measured by the met is then given by:

$$E_m = R_m I = \frac{R_m E_o}{R_{AB} + R_m}$$

**Example : Solution?**


$$E_m = R_m I = \frac{R_m E_o}{R_{AB} + R_m}$$



- It is thus obvious that as  $R_m$  gets larger, the ratio  $E_m/E_o$  gets closer to unity, showing that the design strategy should be to make  $R_m$  as high as possible to minimize disturbance of the measured system.
- Disturbance errors are usually present in passive instruments where energy needs to be withdrawn from the system in the measurement process.
- It is often the reason for the use of alternative active instruments such as digital voltmeters, where the inclusion of auxiliary power greatly improves performance.


#### 4) Errors due to environmental inputs

- ❑ An environmental input is defined as an apparently real input to a measurement system that is actually caused by a change in the environmental conditions surrounding the measurement system.
- ❑ The magnitude of environment-induced variation is quantified by the two constants known as **sensitivity drift** and **zero drift**, both of which are generally included in the published specifications for an instrument.




#### Errors due to environmental inputs

- ❑ Variations of environmental conditions away from the calibration conditions are sometimes described as modifying inputs to the measurement system.
- ❑ When such modifying inputs are present, it is often difficult to determine how much of the output change in a measurement system is due to a change in the measured variable and how much is due to a change in environmental conditions.



## Errors due to environmental inputs

- ❑ In any general measurement situation, it is very difficult to avoid environmental inputs, because it is either impractical or impossible to control the environmental conditions surrounding the measurement system.
- ❑ **System designers are therefore charged with the task of either reducing the susceptibility of measuring instruments to environmental inputs or, alternatively, quantifying the effect of environmental inputs and correcting for them in the instrument output reading.**



## 5) Wear (اهتراء) in instrument components

- ❑ Systematic errors can frequently develop over a period of time because of wear in instrument components.
- ❑ Recalibration often provides a full solution to this problem.



Hardening of softening of the spring used in the scale



## 6) Connecting leads

- In connecting together the components of a measurement system, a common source of error is the failure to take proper account of the resistance of connecting leads (or pipes in the case of pneumatically or hydraulically actuated measurement systems).
- For instance, in typical applications of a resistance thermometer, it is common to find that the thermometer is separated from other parts of the measurement system by perhaps 100 metres.
- The resistance of such a length of 20 gauge copper wire is  $7\Omega$ , and there is a further complication that such wire has a temperature coefficient of  $1\text{m}\Omega / ^\circ\text{C}$ .
- Therefore, careful consideration needs to be given to the choice of connecting leads.

## Reduction of systematic errors

- The prerequisite for the reduction of systematic errors is a complete analysis of the measurement system that identifies all sources of error.
- Simple faults within a system, such as bent meter needles and poor cabling practices, can usually be readily and cheaply rectified once they have been identified.
- However, other error sources require more detailed analysis and treatment.
- Various approaches to error reduction are considered in the next slides.

## Methods for Reduction of systematic errors

### 1) Careful instrument design


- ❑ Careful instrument design is the most useful method in dealing with environmental inputs.
- ❑ This aims at reducing the sensitivity of an instrument to environmental inputs to as low a level as possible.
- ❑ For instance, in the design of strain gauges, the element should be constructed from a material whose resistance has a very low temperature coefficient (i.e. the variation of the resistance with temperature is very small).
- ❑ However, errors due to the way in which an instrument is designed are not always easy to correct, and a choice often has to be made between the high cost of redesign and the alternative of accepting the reduced measurement accuracy if redesign is not undertaken.

## Methods for Reduction of systematic errors

### 2) Method of opposing inputs


- ❑ The method of opposing inputs compensates for the effect of an environmental input in a measurement system by introducing an equal and opposite environmental input that cancels it out.

- ❑ One example of how this technique is applied is in the type of millivolt meter shown.
- ❑ It consists of a coil suspended in a fixed magnetic field produced by a permanent magnet.
- ❑ When an unknown voltage is applied to the coil, the magnetic field due to the current interacts with the fixed field and causes the coil (and a pointer attached to the coil) to turn. (sec2 wed 20-2)



## Method of opposing inputs


- ❑ If the coil resistance  $R_{\text{coil}}$  is sensitive to temperature, then any temperature change in the environment will alter the value of the coil current for a given applied voltage and so alter the pointer output reading.
- ❑ Compensation for this is made by introducing a compensating resistance  $R_{\text{comp}}$  into the circuit, where  $R_{\text{comp}}$  has a temperature coefficient that is equal in magnitude but opposite in sign to that of the coil.
- ❑ Thus, the total resistance remains approximately the same in response to a temperature change.



## Reduction of systematic errors


### 3) High-gain feedback

- ❑ The benefit of adding high-gain feedback to many measurement systems is illustrated by considering the case block diagram of the millivoltmeter shown.
- ❑ In this system, the unknown voltage  $E_i$  is applied to a coil of torque constant  $K_c$ , and the induced torque turns a pointer against the restraining action of a spring with spring constant  $K_s$ .
- ❑ The effect of environmental disturbance on the motor and spring constants is represented by variables  $D_c$  and  $D_s$ .




## High-gain feedback

- ❑ In the absence of environmental inputs, the displacement of the pointer  $X_0$  is given by:  $X_0 = K_c K_s E_i$ .
- ❑ However, in the presence of environmental inputs, both  $K_c$  and  $K_s$  change, and the relationship between  $X_0$  and  $E_i$  can be affected greatly. Therefore, it becomes difficult or impossible to calculate  $E_i$  from the measured value of  $X_0$ .



## High-gain feedback

- ❑ Consider now what happens if the system is converted into a high-gain, closed-loop one, as shown in the, by adding an amplifier of gain constant  $K_a$  and a feedback device with gain constant  $K_f$ .
- ❑ Assume also that the effect of environmental inputs on the values of  $K_a$  and  $K_f$  are represented by  $D_a$  and  $D_f$ .
- ❑ The feedback device feeds back a voltage  $E_0$  proportional to the pointer displacement  $X_0$ .
- ❑ This is compared with the unknown voltage  $E_i$  by a comparator and the error is amplified.



□ Writing down the equations of the system, we have:

$$E_o = K_f X_o$$


$$X_o = (E_i - E_o) K_a K_c K_s$$

$$X_o = (E_i - K_f X_o) K_a K_c K_s$$

$$X_o = E_i K_a K_c K_s - K_f K_a K_c K_s X_o$$

$$X_o (1 + K_f K_a K_c K_s) = E_i K_a K_c K_s$$

$$X_o = \frac{K_a K_c K_s}{(1 + K_f K_a K_c K_s)} E_i$$



If  $K_a$  is made very large (it is a high-gain amplifier),

$$K_f K_a K_c K_s \gg 1$$

$$X_o \cong \frac{1}{K_f} E_i$$

## High-gain feedback

$$X_o \cong \frac{1}{K_f} E_i$$

- This important result shows that the relationship between the output,  $X_o$ , and the input,  $E_i$ , has been reduced to one that involves only  $K_f$ .
- The sensitivity of the gain constants  $K_a$ ,  $K_c$  and  $K_s$  to the environmental inputs  $D_a$ ,  $D_m$  and  $D_s$  has thereby been rendered irrelevant, and we only have to be concerned with one environmental input  $D_f$ .

## High-gain feedback

$$X_o \cong \frac{1}{K_f} E_i$$

- It is usually easy to design a feedback device that is insensitive to environmental inputs: this is much easier than trying to make a coil or spring insensitive.
- Thus, high gain feedback techniques are often a very effective way of reducing measurement system's sensitivity to environmental inputs.
  
- One potential problem, however, is that there is a possibility that high-gain feedback will cause instability in the system.
- Therefore, any application of this method must include careful stability analysis of the system.

## Methods for Reduction of systematic errors

### 4) Intelligent (Smart) Instruments

- Intelligent instruments contain extra sensors that measure the value of environmental inputs and automatically compensate the value of the output reading.
  
- They have the ability to deal very effectively with systematic errors in measurement systems, and errors can be attenuated to very low levels in many cases

## **Methods for Reduction of systematic errors**

### **5) Calibration**

- Instrument calibration is a very important consideration in measurement systems as all instruments suffer drift in their characteristics, and the rate at which this happens depends on many factors, including environmental conditions in which instruments are used and the frequency of their use.
- Thus, errors due to instruments being out of calibration can usually be rectified by increasing the frequency of recalibration.

## **Quantification of systematic errors**


- Once all practical steps have been taken to eliminate or reduce the magnitude of systematic errors, the final action required is to estimate the maximum remaining error that may exist in a measurement due to systematic errors.
- The usual course of action is to assume mid-point environmental conditions and specify the maximum measurement error as  $\pm x\%$  of the output reading to allow for the maximum expected deviation in environmental conditions away from this mid-point.
- Data sheets supplied by instrument manufacturers usually quantify systematic errors in this way, and such figures take account of all systematic errors that may be present in output readings from the instrument.

# Random Errors

## Quick Review (self study)

### Random Errors


- ❑ Random errors in measurements are caused by unpredictable variations in the measurement system.
- ❑ They are observed as small perturbations of the measurement either side of the correct value, i.e. positive errors and negative errors occur in approximately equal numbers for a series of measurements made of the same constant quantity.






## Statistical Analysis of Measurements Subject to Random Errors

- Random errors can largely be eliminated by calculating the average of a number of repeated measurements, provided that the measured quantity remains constant during the process of taking the repeated measurements.



## Statistical Analysis of Measurements Subject to Random Errors

- The degree of confidence in the calculated mean/median values can be quantified by calculating the standard deviation or variance of the data.



## Mean and Median Values

- The average value of a set of measurements of a constant quantity can be expressed as either the mean value or the median value. As the number of measurements increases, the difference between the mean value and median values becomes very small.
- For any set of  $n$  measurements,  $x_1, x_2, \dots, x_n$  of a constant quantity, the mean given by:

$$x_{mean} = \frac{x_1 + x_2 + \dots + x_n}{n} = \frac{1}{n} \sum x_i$$

- When the measurement errors are distributed equally about the zero error value for a set of measurements, the most likely true value is the mean value.

## Mean and Median Values

- The median is an approximation to the mean that can be written without having to sum the measurements. The median is the middle value when the measurements in the data set are written in ascending order of magnitude. For a set of  $n$  measurements,  $x_1, x_2, \dots, x_n$  of a constant quantity, written down in ascending order of magnitude, the median value is given by:

$$x_{median} = \begin{cases} x_{(n+1)/2} & n \text{ is odd} \\ \frac{x_{n/2} + x_{(n+2)/2}}{2} & n \text{ is even} \end{cases}$$

- Thus, for a set of 9 measurements  $x_1, x_2, \dots, x_9$  arranged in order of magnitude, the median value is  $x_5$ . For an even number of measurements, the median value is midway between the two centre values, i.e. for 10 measurements  $x_1, x_2, \dots, x_{10}$ , the median value is given by:  $(x_5 + x_6)/2$

### Example 3

- The length of a steel bar is measured by two sets of observers and the following two sets measurements were recorded (units mm). Find the mean and median for each data set.

#### Measurement set A, 11 observers

398 420 394 416 404 408 400 420 396 413 430

#### Measurement set B, 14 observers

409 406 402 407 405 404 407 404 407 407 408 405  
412

### Standard Deviation and Variance

- Instead of expressing the spread of measurements simply as the difference between the largest and smallest value, a much better way of is to calculate the variance or standard deviation of the measurements. We start by calculating the deviation (error)  $d_i$  of each measurement  $x_i$  from the mean value  $x_{mean}$

$$d_i = x_i - x_{mean}$$

**The variance  $V$  is then given by:**


$$V = \frac{d_1^2 + d_2^2 + \dots + d_n^2}{n-1} = \frac{1}{n-1} \sum (x_i - x_{mean})^2$$

**and the standard deviation**

$$\sigma = \sqrt{V} = \sqrt{\frac{d_1^2 + d_2^2 + \dots + d_n^2}{n-1}} = \sqrt{\frac{1}{n-1} \sum (x_i - x_{mean})^2}$$



## Graphical data analysis techniques – frequency distributions

- ❑ The figure shows a histogram for set B of the length measurement data given in example 3, in which the bands chosen are 3mm wide.
- ❑ The scaling of the bands was deliberately chosen so that no measurements fell on the boundary between different bands and caused ambiguity about which band to put them in.
- ❑ It is often useful to draw a histogram of the deviations of the measurements from the mean value rather than to draw a histogram of the measurements themselves.



## Graphical data analysis techniques – frequency distributions

- ❑ As the number of measurements increases, smaller bands can be defined for the histogram, which retains its basic shape but then consists of a larger number of smaller steps on each side of the peak.
- ❑ For example, the histogram shown below is for a sample of a total of 23 length measurements of the bar in example 3. The bands chosen are 2mm wide




## Graphical data analysis techniques – frequency distributions

- The condition that the area under the curve is unity can be expressed mathematically as:

$$\int_{-\infty}^{\infty} F(D)dD = 1$$

- The probability that the error in any one particular measurement lies between two levels  $D_1$  and  $D_2$  can be calculated by measuring the area under the curve contained between two vertical lines drawn through  $D_1$  and  $D_2$ . This can be expressed mathematically as:

$$P(D_1 \leq D \leq D_2) = \int_{D_1}^{D_2} F(D)dD$$




## Graphical data analysis techniques – frequency distributions

- Of particular importance for assessing the maximum error likely in any one measurement is the *cumulative distribution function (c.d.f.)*.
- This is defined as the probability of observing a value less than or equal to  $D_0$ , and is expressed mathematically as:


$$P(D \leq D_0) = \int_{-\infty}^{D_0} F(D)dD$$

- Thus, the c.d.f. is the area under the curve to the left of a vertical line drawn through  $D_0$ , as shown by the left-hand hatched area on the frequency distribution curve.



## Graphical data analysis techniques – frequency distributions

- ❑ The **deviation magnitude  $D_p$**  corresponding with the peak of the frequency distribution curve is the value of deviation that has the greatest probability.
- ❑ ***If the errors are entirely random in nature, then the value of  $D_p$  will equal zero.***
- ❑ Any non-zero value of  $D_p$  indicates systematic errors in the data, in the form of a bias that is often removable by recalibration.



## Gaussian Distribution

- ❑ If the standard deviation is used as a unit of error, the Gaussian curve can be used to determine the probability that the deviation in any particular measurement in a Gaussian data set is greater than a certain value. By substituting the expression for  $F(D)$  from the previous equation into the probability equation

$$P(D_1 \leq D \leq D_2) = \int_{D_1}^{D_2} F(D) dD$$

- ❑ The probability that the error lies in a band between error levels  $D_1$  and  $D_2$  can be expressed as:

$$P(D_1 \leq D \leq D_2) = \int_{D_1}^{D_2} \frac{1}{\sigma\sqrt{2\pi}} e^{(-D^2/2\sigma^2)} dD$$


## Gaussian Distribution

- ❑ Solution of this expression is simplified by the substitution:

$$z = D/\sigma$$


- ❑ The effect of this is to change the error distribution curve into a new Gaussian distribution that has a standard deviation of one ( $\sigma = 1$ ), and a mean of zero.
- ❑ This new form is known as a standard Gaussian curve, and the dependent variable is now  $z$  instead of  $D$ .
- ❑ The equation can now be re-expressed as:

$$P(z_1 \leq z \leq z_2) = \frac{1}{\sqrt{2\pi}} \int_{z_1}^{z_2} e^{-z^2/2} dz$$



## Standard Gaussian tables

- ❑ The previous equation can not be integrated analytically and numerical integration provides the only method of solution.
- ❑ In practice, the numerical integration can be avoided when analyzing data because the standard form of equation, and its independence from the particular values of the mean and standard deviation of the data, means that standard Gaussian tables that tabulate  $G(z)$  for various values of  $z$  can be used.




$$P(z_1 \leq z \leq z_2) = \frac{1}{\sqrt{2\pi}} \int_{z_1}^{z_2} e^{-z^2/2} dz$$

## Standard Gaussian tables

- A standard Gaussian table tabulates  $F(z)$  for various values of  $z$ , is given by:

$$G(z) = \frac{1}{\sqrt{2\pi}} \int_{-\infty}^z e^{(-z^2/2)} dz$$



- Thus,  $G(z)$  gives the proportion of data values that are less than or equal to  $z$ .
- This proportion is the area under the curve of  $F(z)$  against  $z$  that is to the left of  $z$ .

## Standard Gaussian tables

- To evaluate the probability that the error lies in a band between error levels  $D_1$  and  $D_2$ , the expression has to be evaluated as

$$P(z_1 \leq z \leq z_2) = G(z_2) - G(z_1)$$

where

$$z_1 = D_1 / \sigma, \quad z_2 = D_2 / \sigma$$



- The table shows that  $G(z) = 0.5$  for  $z = 0$ . This confirms that, as expected, the number of data values  $\leq 0$  is 50% of the total.
- This must be so if the data only has random errors. It will also be observed that Gaussian tables only gives  $G(z)$  for positive values of  $z$ .
- For negative values of  $z$ , we can make use of the following relationship:

$$G(-z) = 1 - G(z)$$



### Example 8 (Important)

- ❑ An integrated circuit chip contains  $10^5$  transistors. The transistors have a mean current gain of 20 and a standard deviation of 2.
- ❑ Calculate the number of transistors with a current gain between 19.8 and 20.2
- ❑ How many transistors have exactly gain = 19?

### Example 8. Solution

- ❑ An integrated circuit chip contains  $10^5$  transistors. The transistors have a mean current gain of 20 and a standard deviation of 2. Calculate the number of transistors with a current gain between 19.8 and 20.2

$$z_1 = D_1 / \sigma = -0.2 / 2 = -0.1$$

$$z_2 = D_2 / \sigma = 0.2 / 2 = 0.1$$

$$P(z_1 \leq z \leq z_2) = G(z_2) - G(z_1)$$

$$P(-0.1 \leq z \leq 0.1) = G(0.1) - G(-0.1)$$

$$P(-0.1 \leq z \leq 0.1) = G(0.1) - (1 - G(0.1))$$

$$P(-0.1 \leq z \leq 0.1) = 2G(0.1) - 1 = 2 \times 0.5398 - 1 = 0.0796$$

- ❑ Thus  $0.0796 \times 10^5 = 7960$  transistors have a current gain in the range from 19.8 to 20.2.
- ❑ The number of transistors having gain = 19 is zero

## Standard error of the mean

- If several subsets are taken from an infinite data population, then, by the central limit theorem, the means of the subsets will be distributed about the mean of the infinite data set. The error between the mean of a finite data set and the true measurement value (mean of the infinite data set) is defined as the **standard error of the mean,  $\alpha$** . This is calculated as:

$$\alpha = \sigma / \sqrt{n}$$

- The value of  $\alpha$  approaches zero if the number of measurements in the data set expands towards infinity, or if  $\sigma$  approaches 0. The measurement value obtained from a set of  $n$  measurements,  $x_1, x_2, \dots, x_n$ , measurement can then be expressed as:

$$x = x_{mean} \pm \alpha$$

### Example 6

- A set of length measurements consisting of 23 data points has a mean length value  $x_{mean} = 406.5$  with a standard deviation  $\sigma = 1.88$ . Assuming normal distribution of data, express the value of the length as

$$x = x_{mean} \pm e$$

with a confidence limit of 68% ( $\pm \sigma$  boundaries)

### Example 6. Solution

- A set of length measurements consisting of 23 data points has a mean length value  $x_{mean} = 406.5$  with a standard deviation  $\sigma = 1.88$ . Assuming normal distribution of data, express the value of the length as

$$x = x_{mean} \pm e$$

with a confidence limit of

a) 68% ( $\pm \sigma$  boundaries)

b) 95.4% ( $\pm 2\sigma$  boundaries)

$$x = x_{mean} \pm \alpha$$

$$x = x_{mean} \pm \alpha$$

$$\alpha = \sigma / \sqrt{n} = 1.88 / \sqrt{23} = 0.39$$

$$\alpha = 2\sigma / \sqrt{n} = 3.76 / \sqrt{23} = 0.78$$

$$x = 406.5 \pm 0.4$$

$$x = 406.5 \pm 0.8$$

### Estimation of random error in a single measurement

- In many situations where measurements are subject to random errors, it is not practical to take repeated measurements and find the average value.
- Thus, if only one measurement can be made, some means of estimating the likely magnitude of error in it is required.
- The normal approach to this is to calculate the error within 95% confidence limits, i.e. to calculate the value of the deviation D such that 95% of the area under the probability curve lies within limits of  $\pm D$ .
- These limits correspond to a deviation of  $\pm 1.96\sigma$ .

## Estimation of random error in a single measurement

- ❑ Thus, it is necessary to maintain the measured quantity at a constant value whilst a number of measurements are taken in order to create a reference measurement set from which  $\sigma$  can be calculated.
- ❑ Subsequently, the maximum likely deviation in a single measurement can be expressed as: Deviation  $D = \pm 1.96\sigma$ .
- ❑ However, this only expresses the maximum likely deviation of the measurement from the calculated mean of the reference measurement set, which is not the true value as observed earlier.
- ❑ Thus the calculated value for the standard error of the mean has to be added to the likely maximum deviation value.
- ❑ Thus, the maximum likely error in a single measurement can be expressed as: **Error =  $\pm(1.96\sigma + \alpha)$**

## Aggregation of measurement system errors

- ❑ Errors in measurement systems often arise from two or more different sources, and these must be aggregated in the correct way in order to obtain a prediction of the total likely error in output readings from the measurement system.
- ❑ Two different forms of aggregation are required.
- ❑ Firstly, a single measurement component may have both systematic and random errors and,
- ❑ secondly, a measurement system may consist of several measurement components that each have separate errors.

## **Combined effect of systematic and random errors**

- ❑ If a measurement is affected by both systematic and random errors that are quantified as  $\pm x$  (systematic errors) and  $\pm y$  (random errors), some means of expressing the combined effect of both types of error is needed.
- ❑ One way of expressing the combined error would be to sum the two separate components of error, i.e. to say that the total possible error is  $e = \pm (x+y)$ . However, a more usual course of action is to express the likely maximum error as follows:

$$e = \sqrt{x^2 + y^2}$$

- ❑ It can be shown that this is the best expression for the error statistically, since it takes account of the reasonable assumption that the systematic and random errors are independent and so are unlikely to both be at their maximum or minimum value at the same time.

## **Aggregation of errors from separate measurement system components**

- ❑ A measurement system often consists of several separate components, each of which is subject to errors. Therefore, what remains to be investigated is how the errors associated with each measurement system component combine together, so that a total error calculation can be made for the complete measurement system.
- ❑ All four mathematical operations of addition, subtraction, multiplication and division may be performed on measurements derived from different instruments/transducers in a measurement system. Appropriate techniques for the various situations that arise are covered below.

## Error in a sum

- ❑ If the two outputs  $y$  and  $z$  of separate measurement system components are to be added together, we can write the sum as  $S = y + z$ .
- ❑ If the maximum errors in  $y$  and  $z$  are  $\pm ay$  and  $\pm bz$  respectively, one way to express the maximum and minimum possible values of  $S$  as:

$$S_{\max} = (y + ay) + (z + bz); \quad S_{\min} = (y - ay) + (z - bz); \quad \text{or } S = y + z \pm (ay + bz)$$

## Error in a sum

- ❑ This relationship for  $S$  is not convenient because in this form the error term cannot be expressed as a fraction or percentage of the calculated value for  $S$ . Fortunately, statistical analysis can be applied that expresses  $S$  in an alternative form such that the most probable maximum error in  $S$  is represented by a quantity  $e$ , where  $e$  is calculated in terms of the absolute errors as:

$$e = \sqrt{(ay)^2 + (bz)^2}$$

- ❑ Thus,  $S = (y + z) \pm e$ . This can be expressed in the alternative form

$$S = (y + z)(1 \pm f) \quad \text{where } f = e/(y + z)$$

## Example

- A circuit requirement for a resistance of 550  $\Omega$  is satisfied by connecting together two resistors of nominal values 220  $\Omega$  and 330  $\Omega$  in series.
- If each resistor has a tolerance of  $\pm 2\%$ , calculate the tolerance of the resulting resistance.

### Example : Solution

- A circuit requirement for a resistance of 550  $\Omega$  is satisfied by connecting together two resistors of nominal values 220  $\Omega$  and 330  $\Omega$  in series. If each resistor has a tolerance of  $\pm 2\%$ , calculate the tolerance of the resulting resistance.

$$e = \sqrt{(0.02 \times 220)^2 + (0.02 \times 330)^2} = 7.93$$

$$f = 7.93 / 550 = 0.0144$$

- Thus the total resistance  $S$  can be expressed as:

$$S = 550 \Omega \pm 7.93 \Omega \text{ or } S = 550 (1 \pm 0.0144) \Omega, \quad \text{i.e. } S = 550 \Omega \pm 1.4\%$$

## Error in a difference

- If the two outputs  $y$  and  $z$  of separate measurement systems are to be subtracted from one another, and the possible errors are  $\pm ay$  and  $\pm bz$ , then the difference  $S$  can be expressed (using statistical analysis as for calculating the error in a sum and assuming that the measurements are uncorrelated) as:

$$S = (y - z) \pm e \quad \text{or} \quad S = (y - z)(1 \pm f)$$

- where  $e$  and  $f$  are calculated as

$$e = \sqrt{(ay)^2 + (bz)^2}$$

$$f = e/(y - z)$$

### Example

- A fluid flow rate is calculated from the difference in pressure measured on both sides of an orifice plate.
- If the pressure measurements are 10.0 bar and 9.5 bar and the error in the pressure measuring instruments is specified as  $\pm 0.1\%$ , calculate the tolerance of the resulting flow rate measurement.



### Example 10

- A fluid flow rate is calculated from the difference in pressure measured on both sides of an orifice plate. If the pressure measurements are 10.0 bar and 9.5 bar and the error in the pressure measuring instruments is specified as  $\pm 0.1\%$ , calculate the tolerance of the resulting flow rate measurement.

$$e = \sqrt{(0.001 \times 10)^2 + (0.001 \times 9.5)^2} = 0.0138; \quad f = 0.0138/0.5 = 0.0276$$

The resulting flow rate has an error tolerance of 2.76 %

This example illustrates the relatively large error that can arise when calculations are made based on the difference between two measurements.

### Error in a product

- If the outputs  $y$  and  $z$  of two measurement system components are multiplied together, the product can be written as  $P = yz$ . If the possible error in  $y$  is  $\pm ay$  and in  $z$  is  $\pm bz$ , then the maximum and minimum values possible in  $P$  can be written as:

$$P_{\max} = (y + ay)(z + bz) = yz + ayz + byz + aybz;$$

$$P_{\min} = (y - ay)(z - bz) = yz - ayz - byz + aybz$$

- For typical measurement system components with output errors of up to one or two per cent in magnitude, both  $a$  and  $b$  are very much less than one in magnitude and thus terms in  $aybz$  are negligible compared with other terms.
- Therefore, we have  $P_{\max} = yz(1 + a + b)$ ;  $P_{\min} = yz(1 - a - b)$ . Thus the maximum error in the product  $P$  is  $\pm(a+b)$ .

## Error in a product

- Whilst this expresses the maximum possible error in  $P$ , it tends to overestimate the likely maximum error since it is very unlikely that the errors in  $y$  and  $z$  will both be at the maximum or minimum value at the same time. A statistically better estimate of the likely maximum error  $e$  in the product  $P$ , provided that the measurements are uncorrelated, is given by:

$$e = \sqrt{a^2 + b^2}$$

- Note that in the case of multiplicative errors,  $e$  is calculated in terms of the fractional errors in  $y$  and  $z$  (as opposed to the absolute error values used in calculating additive errors).

## Example:

- If the power in a circuit is calculated from measurements of voltage and current in which the calculated maximum errors are respectively  $\pm 1\%$  and  $\pm 2\%$ , what is the maximum likely error in the calculated power value?

**Solution**

$$e = \pm\sqrt{a^2 + b^2}$$

$$e = \pm\sqrt{0.01^2 + 0.02^2}$$

$$e = \pm 0.022$$

$$e = \pm 2.2\%$$

### Error in a quotient

- If the output measurement  $y$  of one system component with possible error  $\pm ay$  is divided by the output measurement  $z$  of another system component with possible error  $\pm bz$ , then the maximum and minimum possible values for the quotient can be written as:

$$Q_{\max} = \frac{y + ay}{z - bz} = \frac{(y + ay)(z + bz)}{(z - bz)(z + bz)} = \frac{yz + ayz + byz + aybz}{z^2 - b^2z^2};$$

$$Q_{\min} = \frac{y - ay}{z + bz} = \frac{(y - ay)(z - bz)}{(z + bz)(z - bz)} = \frac{yz - ayz - byz + aybz}{z^2 - b^2z^2}$$

For  $a \ll 1$  and  $b \ll 1$ , terms in  $ab$  and  $b^2$  are negligible compared with the other terms. Hence:

$$Q_{\max} = \frac{yz(1 + a + b)}{z^2}; \quad Q_{\min} = \frac{yz(1 - a - b)}{z^2}; \quad \text{i.e. } Q = \frac{y}{z} \pm \frac{y}{z}(a + b)$$

### Error in a quotient

- Thus the maximum error in the quotient is  $\pm(a + b)$ .  
However, using the same argument as made above for the product of measurements, a statistically better estimate of the likely maximum error in the quotient  $Q$ , provided that the measurements are uncorrelated, is that given as:

$$e = \sqrt{a^2 + b^2}$$

## Example

- ❑ If the density of a substance is calculated from measurements of its mass and volume where the respective errors are  $\pm 2\%$  and  $\pm 3\%$ , what is the maximum likely error in the density value?

$$e = \pm\sqrt{a^2 + b^2}$$

$$e = \pm\sqrt{0.02^2 + 0.03^2}$$

$$e = \pm 0.036$$

$$e = \pm 3.6\%$$

## Total error when combining multiple measurements

- ❑ The final case to be covered is where the final measurement is calculated from several measurements that are combined together in a way that involves more than one type of arithmetic operation.
- ❑ For example, the density of a rectangular-sided solid block of material can be calculated from measurements of its mass divided by the product of measurements of its length, height and width.
- ❑ The errors involved in each stage of arithmetic are cumulative, and so the total measurement error can be calculated by adding together the two error values associated with the two multiplication stages involved in calculating the volume and then calculating the error in the final arithmetic operation when the mass is divided by the volume.

### Example 12.

- A rectangular-sided block has edges of lengths  $a$ ,  $b$  and  $c$ , and its mass is  $m$ . If the values and possible errors in quantities  $a$ ,  $b$ ,  $c$  and  $m$  are as shown below, calculate the value of density and the possible error in this value.

$a = 100\text{mm} \pm 1\%$ ,  $b = 200\text{mm} \pm 1\%$ ,  $c = 300\text{mm} \pm 1\%$ ,  $m = 20\text{ kg} \pm 0.5\%$ .

Value of  $ab = 0.02\text{ m}^2 \pm 2\%$  (possible error =  $1\% + 1\% = 2\%$ )

Value of  $(ab)c = 0.006\text{ m}^3 \pm 3\%$  (possible error =  $2\% + 1\% = 3\%$ )

Value of  $m/(abc) = 20/0.006 = 3330\text{ kg/ m}^3 \pm 3.5\%$   
(possible error =  $3\% + 0.5\% = 3.5\%$ )

Compare with

$$e = \pm\sqrt{a^2 + b^2 + c^2 + d^2}$$

$$e = \pm\sqrt{0.01^2 + 0.01^2 + 0.01^2 + 0.005^2}$$

$$e = \pm 0.018$$

$$e = \pm 1.8\%$$