


Operating principle

The field current produces the rotor magnetic field \vec{B}_r .



A set of 3 ϕ voltages is applied to the stator windings which produces a set of 3 ϕ currents to flow the stator windings.

The rotor current will produce \vec{B}_r , which rotates at ω_s .

The rotor is rotating by some external means to obtain a magnetic locking between the rotor & stator poles, and then produces a continuous induced torque ($T_{ind} = K \vec{B}_r \times \vec{B}_s$)




at starting



$p = 2, f = 50 \text{ Hz}$
 $\Lambda_1 = \frac{120}{p} F_1$
 $= 3000 \text{ rpm}$

equivalent circuit (Per. phase)



R_A : armature resistance
 X_s : synchronous reactance
 $X_s = X_A + X$
 ↓ ↓
 Reactance of stator windings Reactance of armature reaction

V_ϕ : Phase voltage

Y-connected $\rightarrow V_T = \sqrt{3} V_\phi$

Δ -connected $\rightarrow V_T = V_\phi$

$$E_A = K \phi \omega_s$$

↓
Induced voltage

Back EMF
EMF


KVL in the armature circuit

$$\vec{E}_A = \vec{V}_\phi - jX_s \vec{I}_A - R_A \vec{I}_A$$

OR $\vec{V}_\phi = \vec{E}_A + R_A \vec{I}_A + jX_s \vec{I}_A$

⊗ Phasor Diagrams

θ : PF angle



$$T_{ind} = K B_r \times B_s = K B_r \times B_{act}$$

$$T_{ind} = K B_r B_{act} \sin \delta$$


δ : Torque angle

\vec{B}_r : ~~current~~ corresponds to E_A


\vec{B}_{act} : corresponds to \vec{V}_ϕ

$$\vec{B}_s = \parallel (-jX_s \vec{I}_A)$$


"Armature reaction"



"generator"



Torque - speed characteristics



Pull-out Torque & T_L 's the maximum operating torque of synchronous motor

$$T_{max} = (2.5 - 3) T_r$$

$$\text{Speed Regulation} = SR = \frac{M_{NL} - \gamma_{FI}}{\gamma_{FI}} \times 100\%$$

$$\gamma_{NL} = \gamma_{FI} = \gamma_T = \frac{120}{P} \text{ Pk}$$

$$SR = 0\%$$

Torque equations

$$T_{ind} = \frac{3 V_{\phi} E_A \sin \delta}{X_s \omega_s} \Rightarrow T_{max} = \frac{3 V_{\phi} E_A}{X_s} \quad \delta = 90^\circ$$

If $T_{load} > T_{max} \Rightarrow$ The motor will lose synchronism
 \Rightarrow "slipping pole phenomenon"

⊗ Effect of load changes


$$T_{ind} = \frac{3 V_{\phi} E_A}{X_s \omega_s} \sin \delta$$

$$T_{ind} - T_{load} = J \frac{d\omega_m}{dt} \quad \text{inertia}$$

$T_{load} \uparrow \Rightarrow \omega_m \downarrow \Rightarrow \delta \uparrow \Rightarrow T_{ind} \uparrow \Rightarrow \omega_m \uparrow$ until it reaches synchronous speed

⊗ Phasor


Phasor



V₁ = 0


T_{ind} PA is very high & it is in Cos δ
 . . . IA Load are as V, is Ie 1

$P \propto I A \cos \phi$



Effect of Load changes

$$T_{ind} = \frac{3 V_t E_A \sin \delta}{X_s \omega_s}$$



$T_{ind} - T_{Load} = J \frac{d\omega_r}{dt}$ $\omega_r = \text{Rotor speed}$

$T_{Load} \uparrow \Rightarrow \omega_r \downarrow \Rightarrow \delta \uparrow \Rightarrow T_{ind} \Rightarrow \omega_r \uparrow$ until it reaches ω_s , but at large δ

Load $\uparrow \Rightarrow$ The PF becomes less leading \rightarrow unity \rightarrow lagging \rightarrow more lagging

تغير التردد وقيمة P →

Effect of I_F changes


Assume P is constant

$$P = \frac{3V_\phi EA \sin \delta}{X_s} = 3V_\phi I_A \cos \theta = \text{constant}$$

$$EA \sin \delta = \text{constant} \quad \& \quad I_A \cos \theta = \text{constant}$$


لقد

Try to increase I_F [EA]



$$E_A = k \phi \omega_s$$


$I_F \uparrow \Rightarrow E_A \uparrow \Rightarrow$ PF becomes less lagging \rightarrow unity \rightarrow leading
 \rightarrow More & More leading



$$S \downarrow = V I \downarrow$$

$$S = \sqrt{P^2 + Q^2}$$

V-curves of synchronous motors.



$$P_3 > P_1 > P$$

its a data Represent
the armature current
and field current

when $E_A \cos \delta < V_\phi \Rightarrow$ Lagging PF \Rightarrow Q is consumed
 \Rightarrow under-excited process


when $E_A \cos \delta > V_\phi \Rightarrow$ PF is Leading
 \Rightarrow Q is supplied
 \Rightarrow over-excited process

Synchronous Condenser or Synchronous Capacitor


Its a synchronous motor without its shaft operated at no-load ($P=0$) & over excited (Q is supplied) it was used historically a power factor correction device.

$$P=0 \Rightarrow P = \frac{3V_\phi E_A \sin \delta}{X_s} = 3V_\phi I_A \cos \theta$$

$$P=0 \Rightarrow \delta=0 \text{ } \theta=90^\circ$$




Power Factor correction can be achieved by :-




- 1) synchronous Condenser
- 2) static capacitors
- 3) using power electronics

3



Example 208V, 45KVA, ab PF leading, Δ -connected, 60Hz, synchronous machine has $X_s = 2.5 \Omega$ & $R_A = 0$ its friction and winding losses are 1.5kW, & its core losses are 1kW, initially the shaft is ~~supplying~~ supplying a 15 hp load, and the motor PF is 0.8 leading.
 $1 \text{ hp} = 746 \text{ W}$

- a) Find the values of \vec{I}_ϕ , I_L & \vec{E}_A ?
- b) Assume that shaft load is now increased to 30 hp, Find \vec{I}_ϕ , I_L & \vec{E}_A , what is the new motor PF ?



KVL in the Armature circuit.

$$208 \angle 0^\circ = j2.5 \vec{I}_\phi + \vec{E}_A$$

$$P_{out} = (15)(746) = 11.19 \text{ kW}$$

$$P_{in} = 11.19 + 2.5 = 13.69 \text{ kW} = 3 V_\phi I_\phi \text{ PF}$$

$$I_\phi = \frac{(13.69 \times 10^3)}{(3)(208)(0.8)} \left[+ \cos^{-1}(0.8) \right] = 27.4 \text{ [36.27 A]}$$

$$\vec{E}_A = 255 \angle -12.4^\circ \text{ V}$$

$$I_L = \sqrt{3} I_\phi = 47.5 \text{ A}$$

b)

$$208 \angle 0^\circ = j2.5 \vec{I}_\phi + \vec{E}_A \quad \rightarrow \quad K_\phi \omega = E_A = \text{constant}$$

$$P_{in} = \frac{3 V_\phi E_A \sin \delta}{X_s}$$

$$P_{in} = (30)(746) + 2.5 \times 10^3 = 24.82 \text{ kW}$$

$$24.82 \times 10^3 = \frac{(3)(208)(255) \sin \delta'}{2.5}$$

$$\delta' = 23^\circ$$

$$\vec{E}_A = 255 \angle -23^\circ \text{ V}$$


$$\vec{I}_\phi = \frac{208 - 255 \angle -23^\circ}{j2.5} = 41.2 \angle 15^\circ$$

$$PF_{\text{new}} = \cos(0^\circ - 15^\circ) = 0.966 \angle \text{Lead}$$

Wpss and @ ϕ ϕ ϕ
PF

Starting of synchronous Motor

Assume that a 50Hz power is supplied to a two poles synchronous motor



$\omega_s = \text{synchronous speed}$

it will vibrate heavily \Rightarrow overheated

Method to start the synchronous motor

① Using external prime mover

- Run the machines as generation using the prime mover.
- Increase the motor speed up to ω_s
- Disconnect the prime mover.

② Using damper or amortisseur windings


This method will start up the synchronous motor like 3φ induction motor

③ Reducing the electric frequency

$$U_s = \frac{120}{p} f_e$$


Motor as per formula (1) & (2)
 Lock → from 1/3000

when f_e is small \Rightarrow the speed of B_s , will be also small ($n_c = \frac{120}{p} f_e$)
 \Rightarrow The rotor can ~~accelerate~~ accelerate and lock in with B_s .
 \Rightarrow when the motor is started increase the electric frequency gradually up to its normal value.




$$V_\phi \approx EA = K\phi \omega_s \propto f_e$$

$\phi \propto V/f$ \Rightarrow Two voltage must decrease with f_e by the same factor to keep ϕ constant & not let it saturated.




$$\frac{V}{f} = \text{constant}$$

VVVF Drive



ω^* : reference frequency
 v^* : reference voltage



So you can work at Rated Torque at all speeds



CH5 problems 1, 2, 3, 7, 9, 10, 14, 17, 18, 19