# AC Machine Drive

#### AC Machine

1 Induction

2 synchronous

1) Induction Machine Drive

operating principle of induction motor:

\* A 3-# set of voltages is applied to the sheer to produce, Bs, which rotates at synchronous speed, ws.

 $w_i = \frac{\omega_e}{P}$  where  $\omega_e$ : electric radian frequency  $P: Number of Polo pair <math>(P = P^1/2)$ 

Note:  

$$N_{j} = W_{j} \frac{60}{2\pi}$$
  
 $N_{j} = \frac{W_{e}}{P} \left(\frac{30}{\pi}\right)$ 

\* B; passes over the rotor bars and induces voltages in the rotor bars:

\* eind produces a rotor magnetic hield, I,.

\* B, interacts with B, to produce electromagnetic torque, Tex.

\* B; passes over the rotor bars and induces voltages in the rotor bars:

\* eind produces a rotor magnetic hield, I,.

\* B, interacts with B, to produce electromagnetic torque, Tex.

## Rotor types of induction motor

anduching shurt


wound poter

## Rotor types of induction motor

anduching shurt

wound poter

# Equivalent circuit



Rs: stator resistance

Xs: stator reactance (Xs = WeL,)

Stator
inductance

inductance

Rr': rotor resistance referred to stator

Xi: rotor reactance referred to stator

(Xi'= We Lr')

be induction to stator

rotor induction to stator

referred to stator

Xm: Magnetizing reachance

(Xm = We Lm)

Rc: core resistance.

The concept of rotor slip;

$$\sigma = \frac{\omega_{s} - \omega_{m}}{\omega_{s}}; \quad \omega_{s}: synchronous speed \omega_{m}: Rotor's speed \lambda$$

W = 0 W = W - W m Lo slip speed


Vs: L-N voltos Torque equation: 7

 $T = \frac{3 I_1^2 R_1^2}{\omega_0} \sim \frac{3 V_2^2 (R_1 | \omega_1)}{\omega_1 [(R_1 + \frac{R_1^2}{\omega_1})^2 + (X_1 + X_1^2)^2]}$ 

+ -mm -mm - T. R. \( \frac{3}{3} \) \( \text{X} \)  $\overline{I}_{i} \approx \overline{I}_{i} \cdot \overline{V}_{i}$   $= \overline{I}_{i} = \overline{(R_{i} + R_{i})} + j(X_{i} + X_{i})$ N(Rs+Rs')2+(Xs+X)12

### Torque-speed curve

$$T_{e,s} = \frac{3 V_{s}^{2} (R_{r}^{1}/\omega)}{\omega_{r} \left[ \left( R_{s} + \frac{R_{r}^{1}}{\omega} \right)^{2} + \left( X_{s} + X_{r}^{1} \right)^{2} \right]}; \omega$$



$$R_{s}'$$

$$N_{s}' + (x_{s} + x_{s}')^{2}$$

$$3V_{s}^{2}$$

$$2W_{s} \left[R_{s} + \sqrt{R_{s}^{2} + (x_{s} + x_{s}')^{2}}\right]$$

#### Induction motor drive - (Wound Rotor)

- 1) Static Robor Resistance Control
- · Recall the induced torque equation ..

If Rr' is constant = Tea is constant for a given, current.

. Recall the slip equation at Tea, max

$$R_{r_{1}} > R_{r_{2}} > R_{r_{3}} > R_{r_{4}} > R_{r_{5}} > R_{r$$

T = 3 V. 2
2W, [R.+NR. + Xin]


Note :-


Rit = of = Retorn efficiency : (1-0) to

Do Thus, this method is inefficient method of speed control. However, it has an advantage of constant torque operation.

\* the static votor resistance control is implemented using diode bridge and a chopper

Static rotor resistance control " Drive circuit " ld: Filtered current " constant "






P(+): instantaneous power absorbed by R.

The average power absorbed by R.

R\*: Effective Value of R




The RMS Value of ('r,a:


$$I_r = \sqrt{\frac{1}{2\pi}} \int_0^{2\pi} c_{i,a}^2 d(wt) = \sqrt{\frac{2}{2\pi}} c_{i,a}^{12} (\frac{2\pi}{3}) = \sqrt{\frac{2}{3}} (\frac{2\pi}{3})$$

is converted into 3-4 equivalent resistor in the rotor circust by equating their losses as hollows

$$3I_{r}^{2}R_{eq}^{*} = i_{s}^{2}R^{*}; R^{*} = (i-8)R$$

$$3(\frac{2}{3})(i_{s}^{2}R_{eq}^{*} = (i_{s}^{2}R^{*}) \Rightarrow [R_{eq}^{*} = \frac{1}{2}R^{*}]; R_{eq}^{*} = \frac{1}{2}(1-8)R$$





### Control System

$$T_{a,b} = \frac{3 \operatorname{Tr}^{2} \operatorname{Rr}^{2}}{W_{s} \circ \omega}$$


$$\operatorname{Rr}^{2} = \operatorname{constart}^{2}, \quad W_{s} = \operatorname{constart}^{2}$$

$$\operatorname{Tr}^{2} = \frac{1}{a} \operatorname{Tr}^{2}; \quad \operatorname{Tr} = \sqrt{\frac{2}{3}} \quad C_{d}^{2}$$

$$\operatorname{Tr}^{2} = \sqrt{\frac{2}{3}} \quad \frac{1}{a} \quad C_{d}^{2}$$

$$\operatorname{Tr}^{2} = \sqrt{\frac{2}{3}} \quad \frac{1}{a} \quad C_{d}^{2}$$

$$T_{ex} = \frac{3}{\omega_s} \frac{Rr'}{\sigma} \frac{2}{3} \frac{1}{a^2} \left( \frac{1}{a^2} \right) = K \left( \frac{1}{a^2} \right)$$
Constant



Design of Current controller

$$V_{a} = Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_{a}^{2}$$

$$V_{a} = V_{a} - Ldi_{a}^{2} + V_{a} = V_{a} - Ldi_$$

EX: - A 4 pole, 3 hp, 415 V, 50 242, y-connected, 3-d induction motor has the following parameters per phase referred to the stator side:-

 $R_s = R_r' = 0.8 \text{ sz}$ ,  $X_s = X_r' = 3.5 \text{ sz}$ ,  $\alpha = 2.5$ Friction and windage losses = 170 W

(a) Calculate the slip at full boad.  $W_s = \frac{We}{P} = \frac{2\pi \times 50}{z} = 50 \pi \text{ rad/sec}$ 

Tel, = PA6 ; PAG = 3×746+170 = 2408 W

$$\frac{1}{\omega_{s,r}} = \frac{2408}{\omega_{m}} = \frac{3V_{s}^{2}(R_{s}^{1}|\sigma_{r}^{2})}{\omega_{s}\left[\left(R_{s} + \frac{R_{s}^{2}}{\sigma_{r}^{2}}\right)^{2} + \lambda_{eq}^{2}\right]} \qquad 3hp$$

$$\omega_{s} = \frac{\omega_{s} - \omega_{m}}{\omega_{s}} = 1 - \frac{\omega_{m}}{\omega_{s}} \Rightarrow \omega_{m} = (1 - \omega)\omega_{s}$$

$$\frac{2408}{(1 - \omega_{s}^{2})} = \frac{3V_{s}^{2}R_{s}^{1}}{\omega_{s}^{2}} \qquad \omega_{m} = (1 - \omega)\omega_{s}$$

$$\frac{2408}{(1 - \omega_{s}^{2})} = \frac{3\left(\frac{415}{V_{s}^{2}}\right)^{2}\left(\frac{0.8}{\sigma_{r}^{2}}\right)}{\left(\frac{0.8}{U_{s}^{2}} + 0.8\right)^{2} + 7^{2}} \Rightarrow \omega_{s} = 0.0011$$


(b) If the votor is star connected, determine the external pesistance inserted in series with the potor windings such that the slip would increase to four time the value obtained in (a) with full bond torque remains constant.

Rinew Rr = 0.8.2


 $R_{r,nec} = R_{r} + R_{ext} = 0.8 + R_{ext} = 3.2$   $R_{ext} = 2.4 \text{ s.} \quad R_{ext} = \frac{2.4}{a^{2}} = \frac{2.4}{(2.5)^{2}} \text{ s.}$ 

- (2) Static Kramer Drive " Slip Energy Recovery Schem."
- · The poter's efficiency is reduced when a static rotor resistance drive circuit is used. some part of slip power is lost as I'R.
- . This slip power can be recovered and supplied back to the source to improve the overall efficiency of the motor.
- . Slip power = P = op ; Pa = 3 Ir' Rr'
- . This can be done by replacing the Dc chopper and R by a 3-4 controlled rechibier.


### . Structure of static Kramer drive





#### Equivalent circuit of motor with static Kramer drive



The power transferred through the confulled rechiber is given by:  $P_{\cdot} = G_{c} U_{i} = 3I_{c}(\gamma)$ 







Ir, = V6 is - RM; Value of the Main component.

$$P_{i} = (ac V_{i})$$

$$V_{i} = \frac{T}{\sqrt{6}} I_{r_{i}}$$

$$V_{i} = \frac{3V_{6}}{\pi} N_{+} (osd V_{i})$$

$$P_{i} = 3 (N_{+} (osd V_{i}) I_{r_{i}})$$

Final equivelent circust

P: = 3 (M+V, wix) I,

Torque equetion

$$T_{ex} = \frac{3}{\omega_s} I_r^{12} \frac{R_r^1}{\sigma} - \frac{3}{3} \frac{1}{4} \frac{$$

180 > d3>d2>d1>90°

$$T_{ee} = \frac{31r_i}{\omega_i} \left[ \frac{1}{r_i} \frac{Rr}{\sigma} - \frac{a n_i \cos \alpha}{\sigma} V_i \right]$$

The torque can be approximated as

Tex 
$$\frac{3V_s I_{r_s}}{\omega_s}$$
 This is valid by neglecting  $X_r^i, X_s, R_s$  and excitation  $I_{r_s} = \frac{I_{r_s}}{a}$ ;  $I_{r_s} = \frac{\sqrt{6}}{\pi}$  (dc. branch.

$$Ir_{1} = \frac{V_{6}}{a\pi} C_{dc} \implies T_{e,a} \approx \frac{3V_{s}}{\omega_{f}} \frac{V_{6}}{a\pi} C_{dc} = KC_{dc}$$

$$T_{e,a} = KC_{dc}; K = \frac{3V_{6}}{\pi} \frac{V_{s}}{a\omega_{f}}$$

# control system

Design of current controller:-

# Induction Motor Drive - Cago rotor

- 1) stator Voltage Control
- . The torque developed by motors-

$$T = \frac{3\Gamma'^2Rr'}{\omega_{\omega}} \approx \frac{3V^2(Rr'|\omega)}{\omega_{r} [(Rs+Rr'|\omega)^2 + Xe_{r}^2]} \Rightarrow T_{\omega} \propto V_{r}^2$$


. Maximum torque

Tes, max = 
$$\frac{3V_s^2}{2W_s \left[R_s + \sqrt{R_s^2 + \chi_{eq}^2}\right]} \Rightarrow Tes, max \propto V_s^2$$

. Maximum slip

Re!

Omes = NRs+ Xes = Constant



The Variation of motor voltage is obtained by a 3-p

Al Voltage regulator, which is able to change the motor

voltage at Rixed Prequency.

- · The change of voltage is obtained at the exprense of a low pf and considerable amount of harmonics.
- . The harmonics increase the losses and require derating of motor.
- . The motor torque capability is also reduced.
- · Applications: Fan + pump drives.

· structure of 3-4 AC Voltage regulator The gate signals must be synchronized with phase voltages and shifted from each other by 60°


IM

\* The machine operates only in the first quadrant \* By using an appropriate firing angle, the motor starting current (starting) torque is restricted by motor Voltage reduction (soft starter) - increases the motor runtime.

- \* The waveforms of motor voltages and currents are vary in three separate modes over the range of d.
- x If & is constant, the motor voltage and current waveforms vary with the motor PF.

  Therefore, the analysis of 3-4 AC Voltage regulator would be very complex because of interation between the motor and controller.
- \* The controller output voltage (input of motor) depends, on both the state of controller and the state of the motor o Simulation method, must be used.

### Reversible Controller



. The sequence of gating for one direction ( clockwise) T, T, T, T, T, T6 · The sequence of geting Lor counterclockwise retation is TI TertarTy TorTer

EX:- A pump has a torque-speed curve given by The CWm. It is proposed to use a 34 IM. The pump speed is varying by using 34 AC voltage regulator with speed peversible ability. The pump induction motor has u poles and B-connected. It has the following parameters referred to the stator:

Rs = 2.5 sz, Rr' = 4.5 sz, Xs = Xr' = 6 sz, Xm = Very large
The motor ratings are 6 kW, 400 V, 50 Hz, 1400 rpm
Calculate the RMS line voltage applied to the
motor at speed of 1300 rpm.

$$W_{r} = \frac{We}{P} = \frac{2\pi(50)}{2} = 50\pi r/ler$$
,  $N_{1} = \frac{120}{Pi}fe = \frac{120}{4}(50) = 1500$   
 $R_{1} = 4.5 \text{ A}$ ,  $R_{5} = 2.5 \text{ A}$ ,  $X_{4} = 6+6 = 12 \text{ A}$ 


$$T_{ed} = T_L = C \omega_m^2$$

$$T_{ed,r} = T_{L,r} = C \omega_{m,r}^2$$

$$35.28 = \frac{3 \sqrt{2} \frac{4.5}{(2/15)}}{50 \pi \left[ \left[ \frac{4.5}{(2/15)} + 2.5 \right]^{2} + (12)^{2} \right]}$$

solve for V

V = 282.5 V



#### Fan and pump Prive,

· In fan and pump drives, the boad torque varies as the square of speed:

$$T_{L} \propto \omega_{m}^{2} \Rightarrow T_{L} = C\omega_{m}^{2}$$
;  $\omega_{m} = (1-\infty)\omega_{s}$   
 $T_{L} = C(1-\infty)^{2}\omega_{s}^{2}$ , where C is constant.

The torque developed by the motor  $T = \frac{3 \operatorname{Ir}^1 R_r^1}{W_{\sigma}}$ 

. If the Friction and windage torques are neglected, then

$$T_{es} = T_{\perp}$$

$$\frac{3I_{s}^{2}R_{r}^{2}}{\omega_{ov}} = C(1-\sigma^{2})^{2}\omega_{r}^{2}; \quad \omega_{ov} = \infty \omega_{s}$$


$$solve \quad For \quad I_{\perp}$$

$$I_{\perp} = K(1-\sigma^{2}) \quad \forall \sigma \quad ; \quad K = \sqrt{\frac{c\omega_{r}^{3}}{3R_{r}^{2}}}$$

. Maximum motoris current



· Motor's rated current




Let 
$$\mathcal{X} = \frac{T_{s,max}}{T_{s,r}}$$
;  $T_{s,max} = \frac{2}{3\sqrt{3}} \mathcal{K}$ ,  $T_{s,r} = \mathcal{K}(1-\sigma_r) \sqrt{\sigma_r}$ 

- . If the motor rating power = full load power requirement => the motor will be overloaded for speed: less than Ist
- or Typical full-load slips in fan and pump drives V = 0.1 0.2 V = 1.07 1.35 = 0Factor of overloading

  Wm LWm, r Wm, r

8 = 1.07 - 1.35 - Factor of overloading



When a speed varge from  $\omega_{r}$  to  $\frac{2}{3}\omega_{r}$  or to speed less than this is required,  $I_{s,r}$  must be selected as equal to  $I_{s,max}$ .  $G_{r}^{(s)} \stackrel{\circ}{>} I_{s,r} = I_{s,max}$ The speed varge from  $\omega_{r}$  to  $\frac{2}{3}\omega_{r}$  or to speed as equal to  $I_{s,max}$ .

The speed  $I_{s,r}$  is required,  $I_{s,r}$  and  $I_{s,r}$  is  $I_{s,r}$  and  $I_{s,r}$  is  $I_{s,r}$ .

The speed  $I_{s,r}$  is required by the melos  $I_{s,r}$  where  $I_{s,r}$  is  $I_{s,r}$  is  $I_{s,r}$  is  $I_{s,r}$ .

Full load power delivered by the motor < Notar rating power

D Hotor is derated "

Derating factor = DF = 0.74-0.93

. Additional desating should be applied for the reduction of cooling (shaft-mounted from) at low speed;
. Additional desating should be applied for additional harting due to harmonic cosses.

### 3 Variable Frequency Drive

· The klahisnship between synchronous speed and stator electric frequency is given by:-

$$W_s = \frac{w_e}{P} = \frac{2\pi f_e}{P}$$

- . The speed of IH is very close to W, , and Changing W, results in speed Variations.
- . speed control is achieved in the inverter driven IM by means of variable frequency.

. Apart from frequency, the applied voltage need, to be varied to keep the air-gap flux, 2m, constant and not let it saturated.

. The rms value of air-gap flux is

A = L I - P pagnetizing

megnetizing

inductions.

Im = E = E Xm WLm

E (300) JAM

=D Am = Vm \(\frac{E}{\omega\_e Lm} =D\) Am = \(\frac{E}{\omega\_e} \sigma\_\omega\_e \frac{V\_s}{\omega\_e} \sigma\_\omega\_\omega\_e \frac{V\_s}{\omega\_e} \sigma\_\omega\_\o

A number of control strategies have been formulated, depending on how the voltage-to-frequency rations in implemented:

, (i) Constant Volts/H2 control or VVVF

J

Variable Voltage

Variable Frequency.

(ci) Constant air-gap flux control (scalar control)

(iii) Vector Control &

1i) Constant Volts/Hz control (VVVF drive)

m ~ Vs We

To maintain Am constant, Vs has to be maintained we constant -p whenever we is changed to control the speed, Vs has to be changed accordingly to maintain Im constant.

In general, the relationship between V, and We is written as:

 $V_s = K_{vp} W_e + V_o$ ;  $K_{vp} = \frac{V_{s,r}}{W_{e,r}}$ 220 Vo is the offset voltage to overcome the voltage Vs whene drop across Rs at Low speeds

1. .

$$T_{as} = \frac{3V_{s}^{2}(R_{r}^{2}|\sigma)}{W_{r}^{2}[((R_{r}^{2}|\sigma)+R_{s})^{2}+K_{g}^{2}]}$$

$$T_{as,max} = \frac{3V_{s}^{2}}{2W_{r}^{2}[R_{s}+NR_{s}^{2}+K_{g}^{2}]}$$

$$R_{s}^{1}$$

$$R_{s}^{1}$$

$$R_{s}^{1}$$

$$N_{s}^{2}+K_{g}^{2}$$

Tee

As L fu L fo L fo L fo

What when when when the com

when we want to be a com

of so to the com

Pt => We t => W, 1 => Wm t.

Tes = KW.

 $U_{n} = U_{r} - U_{m}$   $U_{n} = W_{r} - U_{m}$   $U_{n} = W_{r} - U_{m}$   $U_{n} = W_{r} - U_{m} = U_{r} - U_{m}$   $U_{n} = U_{r} - U_{m} = U_{r} - U_{m}$   $U_{n} = U_{r} - U_{m} = U_{r} - U_{m}$   $U_{n} = U_{r} - U_{m} = U_{r} - U_{m}$   $U_{n} = U_{r} - U_{m} = U_{r} - U_{m}$   $U_{n} = U_{r} - U_{m} = U_{r} - U_{m}$   $U_{n} = U_{r} - U_{m} = U_{r} - U_{m}$ 


### Drive Circuits

1 6-step inverter with controlled rechiter

$$V_{i,peak} = \frac{2}{\pi} V_{pc}$$

$$V_{i} = \frac{2}{\sqrt{2}\pi} V_{pc} - \frac{\sqrt{2}}{\pi} V_{pc}$$

2) Three-phase inverter inverter




### Drive Circuits

1 6-step inverter with controlled rechiter

$$V_{i,peak} = \frac{2}{\pi T} V_{pc}$$

$$V_{i} = \frac{2}{\sqrt{2}\pi} V_{pc} - \frac{\sqrt{2}}{\pi} V_{pc}$$

2) Three-phase inverter inverter



# Control System

1) Open Loop

 $V_{s}^{+}=K_{v_{p}}W_{e}^{+}+V_{o}$ ;  $K_{v_{p}}=\frac{V_{s,r}}{W_{e,r}}$   $V_{s,m}=(peak)$  stater  $V_{s,m}=(peak)$  stater  $V_{s,m}=(peak)$ 


We to King the Vs, m


Vo We


Vs, m

Vs We


V








# Closed loop (with 3¢ inverter)





Ex:- A 3p Y-connected, bo He, 4 poles IM has the following parameters: Rs=Rs = 0.024 sz, Xs=Xs=0.12 s The motor is controlled using VVVF drive. For an operating frequency of 12 Hz, Calculate

i) The maximum torque as a ratio of its value at the reted

frequency.

T (60H2)

 $\frac{V_s}{ex_{,max}} = \frac{V_s}{v_s} = constant = \frac{V_s}{v_s}$ 

12 He 60 H2


$$\frac{T(12)}{\text{Re}, mex} = \frac{R_s + \sqrt{R_s^2 + (2\pi \times 60 \times \text{Leg})^2}}{R_s + \sqrt{R_s^2 + (2\pi \times 12 \times \text{Leg})^2}} \cdot \frac{12}{60} = 0.68$$

$$\frac{T(60)}{\text{Re}, mex} = \frac{R_s + \sqrt{R_s^2 + (2\pi \times 12 \times \text{Leg})^2}}{R_s + \sqrt{R_s^2 + (2\pi \times 12 \times \text{Leg})^2}} \cdot \frac{12}{60} = 0.68$$

$$x_{eq} = x_c + x_r' = 0.12 + 0.12$$
 @ 60Hz,  $R_s = 0.024 \text{ A}$ 

$$L_{eq} = \frac{0.24}{24 \times 60}$$

7) The starting torque as a repl of its Value et the rated frequency.



$$X = \frac{2V_{s}^{2}}{(R_{s} + R_{s}^{2})^{2} + (2\pi \times 60 \times L_{eq})^{2}} \frac{P_{s}^{2}}{P} (2\pi) f_{e}^{2}$$

$$X = \frac{(R_{s} + R_{s}^{2})^{2} + (2\pi \times 60 \times L_{eq})^{2}}{(R_{s} + R_{s}^{2})^{2} + (2\pi \times 12 \times L_{eq})^{2}} \frac{12}{60} = 2.6$$

## (ii) Constant air-gap flux control

If resolves IH into an equivalent separately excited DC motor in terms of its speed response, but not in terms of decoupling of the flux and torque channels.

x Recell the air-gap Alux linkage equation:  $\lambda_{m} = L_{m} I_{m} = L_{m} \frac{E}{w_{e} L_{m}} = \frac{E}{w_{e}}$   $+ 3 I_{e}^{12} R_{e}^{1}$ 

$$\lambda_{m} = \frac{E}{w_{e}}, \quad T_{el} = \frac{2 \, T_{i}^{2} R_{i}}{w_{o}}$$

$$\frac{1}{T_{i}} = \frac{E}{\frac{R_{i}^{1} + j \, X_{i}^{1}}{\sigma}} = \frac{1}{T_{i}^{2} + \frac{E}{\sqrt{\frac{R_{i}^{1}}{2} + X_{i}^{2}}}}$$

$$\frac{1}{T_{el}} = \frac{3 \, E^{2} \, R_{i}^{1}}{w_{o} \left[ \left( \frac{R_{i}^{1}}{\rho w_{o}} \right)^{2} + X_{i}^{2} \right]} = \frac{3 \, E^{2} \, R_{i}^{1}}{w_{e}^{2} \, w_{e}^{2} \left[ \left( \frac{R_{i}^{1}}{\rho w_{e}} \right)^{2} + L_{i}^{2} \right]}$$

$$\frac{1}{T_{el}} = \frac{3 \, \lambda_{m}^{2} \, R_{i}^{1}}{w_{o}^{2} \, w_{e}^{2} \, w_{e}^{2} \left[ \left( \frac{R_{i}^{1}}{\rho w_{o}} \right)^{2} + L_{i}^{2} \right]}$$

$$\frac{1}{T_{el}} = \frac{3 \, \lambda_{m}^{2} \, R_{i}^{1}}{w_{o}^{2} \, w_{e}^{2} \, w_{e}^{2}$$

Tex = 3PA, R. /(Pw) ) 2+L, "

Tex = 3PA, (R. /(Pw)) 3+L, "

Tex =

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + (L_{r}^{1} + L_{m})^{2}}{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + (L_{r}^{1} + L_{m})^{2}}{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + (L_{r}^{1} + L_{m})^{2}}{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + (L_{r}^{1} + L_{m})^{2}}{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}}}$$


$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}}$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{r}^{1}/|\rho\omega_{\sigma}|)^{2} + L_{r}^{1/2}}}}$$

$$T_{ee} = F_{1}(\omega_{or})$$

$$I_{s} = F_{2}(\omega_{or})$$

# Drive Circuit



Control System Tes = F (Wp) I, = FL (Wa) F, (T\*) F2 (W\*) 1 = VZ I, sin(w++) Lb= 12 I, sin (wet - 211/3)

Lb= | Is sin (wet - 211/3)

Current Contaller

C'= | I I, sin (wet + 24/7)


- SPWM current Contal

- HCC.

### Current Controller

Vom = M Vnc

1) SPWM current control RESaible }





PR: Proportional Resonance

$$PI = k_1 + \frac{k_2}{s}$$

$$PR = k_1 + \frac{krs}{s^2 + \omega^2}$$

$$Error \propto \frac{1}{pI}$$





H

EX:- A 400 V, 50 Hz, 6 pole, 960 rpm, y-connected IM, The parameters per-physe referred to the stator: R, = 0.4 2, Rr = 0.2 sz, X, = X, = 1-5 2, Xm = 30 2 The motor is controlled using constant air-gap Elex controller. i) Ealculate the rated slip, slip speed, and induced voltage or, War, Er  $W_{s,r} = \frac{W_{e,r}}{\rho} = \frac{2\pi x s_0}{3} = 104.72 \ r/sec$ Wm,r = 960 TT = 100-53 r/sec  $\sigma' = \frac{\omega_{1,r} - \omega_{m,r}}{\omega_{1,r}} = \frac{104.72 - 100.53}{104.72} = 0.04$ 

Wor, = or Wf, = 0.04 (104.72) = 4.2 8/fec

$$\frac{E_{r}}{\sqrt{3}} - \frac{400}{\sqrt{3}} + \frac{E_{r}}{\sqrt{3}} + \frac{E_{r}}{\sqrt{3}} + \frac{E_{r}}{\sqrt{3}} + \frac{1}{\sqrt{3}} = \frac{1}{\sqrt{3}}$$

$$\frac{0.4+31.5}{\sqrt{3}} + \frac{1}{\sqrt{3}} + \frac{1}{\sqrt{3}} = \frac{1}{\sqrt{3}} + \frac{1}{\sqrt{3}} = \frac{1}{\sqrt{3}}$$

$$\frac{1}{\sqrt{3}} + \frac{1}{\sqrt{3}} + \frac{1}{\sqrt{3}} = \frac{1}$$

2) calculate the air-gap flux

3) Calculate the rated torque developed by the motor

$$P=3$$
 $P_{m_1} = 0.63$ 
 $P_{n_2} = 0.63$ 
 $P_{n_3} = 0.63$ 
 $P_{n_4} = 0.2$ 
 $P_{n_5} = 0.2$ 
 $P_{n_5} = 9.2$ 

4) Calculate the motor speed and at half the rated to began and 25 Ht.

$$\frac{188}{2} = 3(3)(0.63)^{2} \frac{R_{r}/(pw)}{(0.2/(3w))}$$

$$\frac{188}{2} = 3(3)(0.63)^{2} \frac{(0.2/(3w))}{(0.2/(3w))^{2} + (\frac{1.5}{2\pi x + 5})^{2}}$$
Solve for  $w_{0} = D$   $w_{0} = 1.96$  res/sec

$$w_{m} = w_{s} - w_{0} = \frac{2\pi x + 25}{3} = 1.96 \implies w_{m} = 50.4 \implies r/sec$$

$$I_{s} = I_{m} \sqrt{\frac{(R_{s}')(pw_{s})^{2} + (L_{p}' + L_{m})^{2}}{(R_{s}')(pw_{s})^{2} + L_{s}'^{2}}}$$

$$I_{s} = \frac{\lambda_{m}}{L_{m}} \left[ \frac{\left(0.2/\beta(1.46)\right)^{2} + \left(\frac{31.5}{2\pi x 50}\right)^{2}}{\left(0.1/(3(1.46))\right)^{2} + \left(\frac{1.5}{2\pi x 50}\right)^{2}} \right]$$

 $A_{m} = L_{m} I_{m}$   $A_{m} = 0.63$ 

Lm = 30 2000

### Field Weakening

$$\lambda_{m} = L_{m} I_{m} = L_{m} \frac{E}{x_{m}}$$

$$\lambda_{m} = \frac{E}{\omega_{e}} \approx \frac{V_{s}}{\omega_{e}}$$

When 
$$\omega_m \leq \omega_{m,r} \Rightarrow \lambda_m = \lambda_{m,r}$$
  
when  $\omega_m \geq \omega_{m,r} \Rightarrow v_s = v_{s,r} = \omega_e \lambda_m = \omega_{e,r} \lambda_{m,r}$   
 $\Rightarrow \lambda_m = \lambda_{m,r} \frac{\omega_{e,r}}{\omega_e}$  "Field weakening"

$$I_{s} \approx \frac{V_{s,r}}{\sqrt{\frac{R_{s}^{2} + R_{s}^{2}}{\sigma^{2}} + X_{eq}^{2}}} \qquad Since \quad \sigma' i. \quad Very \quad small}$$

$$I_{s} \approx \frac{V_{s,r}}{\sqrt{\frac{R_{s}^{2} + R_{s}^{2}}{\sigma^{2}} + X_{eq}^{2}}} \qquad I_{s} \approx \frac{\sigma' V_{s,r}}{R_{s}^{2} + W_{s}} = \frac{\rho W_{o} V_{s,r}}{R_{s}^{2} + W_{e}}$$

$$\Rightarrow W_{o} = \left(\frac{R_{s}^{2}}{\rho V_{s,r}}\right) I_{s} \cdot W_{e} \quad \Rightarrow W_{o} \quad increases \quad linearly \quad with \quad W_{e} \quad \text{for a given current}$$

$$T_{al} = \frac{3V_{s,r}^{2}}{\omega_{s}\left[\left(R_{s} + R_{s}^{2}\right)^{2} + X_{eq}^{2}\right]} \cdot \frac{R_{r}^{2}}{\sigma^{2}}$$


since or is small

Tes 
$$\frac{3V_{s,r}}{W_{s}R_{r}^{1}}\frac{\omega_{s}}{\omega_{s}} = \frac{3V_{s,r}}{W_{s}^{2}R_{r}^{1}}\frac{\omega_{o}}{W_{s}^{2}} = \frac{3P^{2}V_{s,r}}{R_{r}^{1}}\frac{\omega_{o}}{\omega_{e}^{2}}$$

$$\Rightarrow T_{es} \propto \frac{1}{\omega_{e}}$$

-) The developed power by the motor is constant

D) Thus, for Wey, We, = The Scalar controller gives constant constant power operation.




In the constant power mode, the torque keeps decreasing inversely with speed. At critical speed, wmc, the maximum tarque is reached. Any aftempt to operate beyond this speed will stall the motor. This is the limit of constant power region.

To prevent the torque from exceeding Teyman, the machine is operated at constant slip speed. In this case, the motor current reduces inversely with speed, and the torque decreases inversely at the speed square.

De motor characteristic.

Wo = Rr I, We Test = 
$$\frac{3p^2V_{s,r}}{p_{s,r}}$$
 Wow workfunt


 $V_{s,r} = \frac{3p^2V_{s,r}}{p_{s,r}}$  Wow workfunt



### Synchronous Machine Drive

operating principle of SM


- . The hield current produces Br.
- · A set of 10 voltages in applied to the stator, which produces a 20 current, to below in the stator windings.




- · The currents produce a uniform rotating magnetic hield, B, which rotates at Ws.
- The votor is poteting by some external means at start to obtain a magnetic locking between the stator and poter poles, and then produce a continuous induced torque (Tu, = KB, KB, I

Classifications of SMI:-


- 1) Wound Reld Cylinderical
- 2) Permanent Magnet
- 3) Wound Rield Salient-Pole
- 4) Reluctance





. The peak of rotating mmf produced by the rm current, If flowing through  $N_a$  turns is  $F_1 = \frac{3}{2} N_a (\sqrt{2} I_z)$ . The peak of rotating mmf produced by a dc current  $I_F$  flowing through  $N_f$  turns is  $F_2 = N_f I_F$   $F_1 = F_1 \quad \text{D} \quad I_g = N I_F \quad \text{where} \quad N = \frac{\sqrt{2}}{3} \frac{N_f}{N_a}$ 



### phasor diagram








### Torque Equations

$$T_{a,s} = \frac{3V_s V_s}{X_s \omega_s} \sin s$$




$$\mathbb{Z} = \frac{3 \sqrt{y}}{\omega_{\xi} \times s} \sin s$$


$$T_{al} = \frac{3 \times I_m I_g}{\omega_i \times i_g} sins$$

$$T_{ae} = \frac{3 \times 1 - 1_{p}}{\omega_{i} \times 1_{p}} \sin \delta = \frac{3 \times 1 - 1_{p}}{\omega_{i}} \sin \delta$$

文元为ix. ① 元, 三次

The = 
$$\frac{P_{air-gas}}{\omega_s} = \frac{3 V_p I_s \cos 8}{\omega_s}$$





## Torque-speed characteristic

Tea, near pull out porque porque porque porque porque porque de proportion de proporti

¿ laggin, Meterin, Braking

power

Lurve

#### Variable Frequency Drive

- + The SM runs of Lixed speed equal to Ws; therefore, its speed can be controlled by the control of its supply frequency.
- with variable frequency control, the SH may operate in two modes:
  - 1) open loop U/f control
  - 2) closed loop V/f Control
- + The speed must be changed gradually to allow the notor to track the changes in the revolving field speed.

$$\lambda_{m} = L_{s} I_{m}$$

$$I_{m}^{\prime} = \frac{V_{s}}{X_{s}} = \frac{V_{s}}{W_{c}} \lambda \frac{V_{s}}{W_{c}}$$

$$\lambda_{m} \lambda \frac{V_{s}}{W_{c}}$$

$$\omega_{m} \in \omega_{m_{s}r} \Rightarrow \lambda_{m} = \lambda_{m_{s}r} \omega_{m_{s}r}$$

$$\omega_{m} \geq \omega_{m_{s}r} \Rightarrow \lambda_{m} = \lambda_{m_{s}r} \omega_{m_{s}r} \qquad ; \quad \omega_{m}$$

. Torque-speed characteristics of SM with variable Lrequency control.


#### Drive Circuits


- 1) 6-step inverter with controlled pechihier
- 2) Three-phase inverter.

① Open loop (ontrol

6-she


10 write 
$$\frac{1}{\sqrt{1-1}} \frac{1}{\sqrt{1-1}} \frac{1}{$$






 $m_{a}^{*} = \sqrt{2} V_{s} \sin(\omega_{e}^{*}t) \frac{2}{V_{DC}}$   $m_{b}^{*} = \sqrt{2} V_{s} \sin(\omega_{e}^{*}t - 2\pi/2) \frac{2}{V_{DC}}$   $m_{c}^{*} = \sqrt{2} V_{s} \sin(\omega_{e}^{*}t + 2\pi/3) \frac{2}{V_{DC}}$ 

M = 2V2 Vs VDC Lo mode la hon inden






 $m_{a}^{*} = \sqrt{2} V_{s} \sin(\omega_{e}^{*}t) \frac{2}{V_{DC}}$   $m_{b}^{*} = \sqrt{2} V_{s} \sin(\omega_{e}^{*}t - 2\pi/2) \frac{2}{V_{DC}}$   $m_{c}^{*} = \sqrt{2} V_{s} \sin(\omega_{e}^{*}t + 2\pi/3) \frac{2}{V_{DC}}$ 


M = 2V2 Vs VDC Lo mode la hon inden (2) Closed loop Advantages

V Fast dynamic response for speed commands and load changes

v The power factor of wourd hield SM can be controlled by controlling its kild current, IF.



Lontral system (a = V2 I sin (w + + 8 )



## 2) Permanent Magnet Synchronou: Motor (PHSM)

· Equivalent circuit

$$\overrightarrow{V}_{i} = \overrightarrow{I}_{i} = \overrightarrow{I}_{i} - (s + 9i)$$

$$\overrightarrow{V}_{i} = \overrightarrow{I}_{i} - (s + 9i)$$

$$\overrightarrow{V}_{i} = \overrightarrow{V}_{i} - (s + 9i)$$

$$\overrightarrow{V}_{i} = \overrightarrow{V}_{i} - (s + 9i)$$

$$\overrightarrow{V}_{i} = \overrightarrow{V}_{i} - (s + 9i)$$

· The use of PH for excitation eleminates brushes a slippings, and the associated maintenance. It also eleminates the field copper losses and the need for a DC sousce.

- Recause of constant Lield current, the PF can not be controlled. If the Lield is designed to obtain a unity PF at Lull load, the motor operater at very low PF (leading) at light loads, resulting in poor efficiency.
- . PUSM: are expensive because of high cost of magnets and votor assembly.

Prive Circuits

- 1) 6-step inverter with controlled rechiber
- 2) Three-phase inverter
- 1) open boops control "similar to wound tield SM "

3 Closed Loop Control

It = constant = D PF is uncontrolled

$$V_{s}$$

$$I_{g} sin s = I_{s} cos \theta$$

$$I_{m} - I_{g} cos s = I_{s} sin \theta$$

$$I_{s} = \sqrt{I_{s}^{2} + I_{m}^{2} - 2 I_{m}} I_{g} cos s$$

$$I_{s} = 2Pl_{s} I_{g} I_{m} sin s$$

$$Com \leq Com_{s} = D I_{m} = I_{m,r}$$

$$Com \geq Com_{s} = D I_{m} = I_{m,r}$$

$$Com \leq Com_{s} = D I_{m} = I_{m,r}$$

$$Com_{s} = D I_{m} = I_{m,r}$$

$$Com_{s} = D I_{m} = I_{m,r}$$

$$Com_{s} = D I_{m} = I_{m,r}$$

(3) closed loop control

Ij' = constant = D PF is uncontrolled


$$\frac{\overline{V}_{s}}{V_{s}}$$

$$I_{s} = \sqrt{I_{s}^{2} + I_{m}^{2} - 2I_{s}^{2} I_{m}^{2} Cois}$$

$$I_{ae} = 3PL, I_{s}^{2} I_{m}^{2} SinS$$

System Control I, = N I, 2 + I, 2 = 2 I, I sins ( = VZ I, Sin (we+ 6")

# 3) Wound Rild (Salient Pole) Synchronous



x y d g

Bi: stator field non-salient pole

Be: States hield salient poles

- . The poter magnetic Rield induces a voltage in the states, which peaks in the wires directly under the pole faces.
- when a set of 24 voltages is applied to the stator windings, a stator current will flow to produce a stator mmf, Fs.
- Fi produces B. (Stotor flux). However, the direct component of Fi produces mon flux than the quadratum component since the reluctance at the direct-axis Path is lower than the reluctance of the quadratum axis path. F =  $\phi$  R  $\phi$  >  $\phi$  >  $\phi$  must pure pure axis path. F =  $\phi$  R  $\phi$  >  $\phi$  >  $\phi$  >  $\phi$  must pure pure axis path.

Bsg produces the armature vollage Va Bod produces the armatum voltage Be interacts with Brief to produce Tex such that

Tex Such that

Tex & Brief

Tex &

### Phasor diagram and torque equation

601 A6013 - JinA sins = 601 (A+13)

I To V. X Isa V. Y. S. Isa V. S. Isa

 $I_s(os(\theta-s)) = I_{sd}$   $I_s(os(\theta-s)) = I_{sq}$ 

$$I_s(os(0-s))(oss) = I_{sd}(oss) - \cdots 0$$
  
 $I_s(os(0-s))(oss) = I_{sd}(oss) - \cdots 0$ 

 $0-@ \Rightarrow I_{s} cos \theta = I_{s} cos s - I_{s} sin s - 3$   $V_{s} sin \delta = X_{s} I_{s} \Rightarrow I_{s} = \frac{V_{s} sin \delta}{X_{s} \delta} - \frac{3}{2}$   $V_{s} cos \delta - V_{s} = X_{s} I_{s} \Rightarrow I_{s} = \frac{V_{s} cos \delta}{X_{s} \delta} - \frac{3}{2}$   $V_{s} cos \delta - V_{s} = X_{s} I_{s} \Rightarrow I_{s} \Rightarrow I_{s} \Rightarrow V_{s} cos \delta - \frac{3}{2}$ 


$$I_{c} cos\theta = \left(\frac{V_{s} sin \delta}{X_{cq}}\right) coss - \left(\frac{V_{r} coss - V_{g}}{X_{sd}}\right) sin \delta$$

= 
$$\frac{V_2}{X_{sd}}$$
 sins +  $\frac{V_2}{X_{sg}}$  sins coss -  $\frac{V_2}{X_{sd}}$  sins coss | sins coss

$$\overline{I}_{s} \cos \theta = \frac{V_{g}}{X_{id}} \sin \delta + \left(\frac{1}{X_{sq}} - \frac{1}{X_{id}}\right) \frac{V_{s}}{z} \sin z \delta$$

There = 
$$\frac{P_{in}}{\omega_s} = \frac{3V_s I_s cos\theta}{\omega_s}$$
 =  $\frac{3V_s V_x}{\chi_{sd} \omega_s} \sin s + \frac{3}{2} \frac{V_s I_s}{\omega_s} \left[\frac{1}{\chi_{sq}} - \frac{1}{\chi_{sd}}\right] \sin s$ 

excitation.



# 4) Synchronous Reluctance Motor

- . It is similar to salient pole motor except that there is no hield winding on the rotor.
- . The armstum circuit, which produces retains magnetic held in the air-gap, induces a Keld in the roter that has a fendency to align with the armsture Rield.
- . The reluctance maters are very simple and are used in applications where a number of motors are required to pate to in synchronizm.

Because of the absence of the hield excitation, the entire Im required to produce the air-gap flux has to come from the armeter supply the machine has low lagging PF (0.65-0.75) at full load.

. The torque developed by the motor is:-

 $T_{ae} = \frac{3}{2} V_1 \left[ \frac{1}{X_{19}} - \frac{1}{X_{sa}} \right] Sinzd$ 

. The pull out torque in reached at &= 45°

