

Part 3 (35 Points, 30 Minutes)

Question 7

- a) The double-angle bracing diagonal is subjected to axial force consisting of the service dead and live load as shown. Design a bolted connection with the 7/8" gusset plate using 3/4"-A325-N bolts.
- b) Detail the connection and check whether the diagonal member is still adequate.

